

From: "Trump, Julee M." <trumpjm@cdmsmith.com>  
To: "Sheldrake, Sean" <sheldrake.sean@epa.gov>  
"Zhen, Davis" <Zhen.Davis@epa.gov>  
CC: younghs@cdmsmith.com  
"Scott Coffey" <coffeyse@cdmsmith.com>  
Date: 6/17/2018 2:51:37 PM  
Subject: Re: Portland Harbor Surface Sediment Sampling  
Attachments: [20180617\\_143834.jpg](#)

---

Sean and Davis,  
Aliquots were cooled on ice while sampling SG-B042 alt1 due to warm temperatures and hard sediment sampling conditions.

Julee

Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----

From: "Trump, Julee M." <trumpjm@cdmsmith.com>  
Date: 6/17/18 10:57 AM (GMT-08:00)  
To: "Sheldrake, Sean" <sheldrake.sean@epa.gov>, "Zhen, Davis" <Zhen.Davis@epa.gov>  
Cc: "Young, Howard S." <younghs@cdmsmith.com>, "Coffey, Scott" <CoffeySE@cdmsmith.com>  
Subject: Re: Portland Harbor Surface Sediment Sampling

Sean and Davis

Find attached photos at locating SH-B031 (RM2.6E).

Only the edge (~5 ft) of the 25 ft radius is accessible because the target point is on private property and a pier partially blocks part of the sample area.

1st photo: area photo of pier with sampler just inside the 25 ft

2nd photo: screen shot of map showing 25 and 50 ft radius, property line and grab points.

Thank you,  
Julee

Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----

From: "Trump, Julee M." <trumpjm@cdmsmith.com>  
Date: 6/17/18 10:32 AM (GMT-08:00)  
To: "Sheldrake, Sean" <sheldrake.sean@epa.gov>, "Zhen, Davis" <Zhen.Davis@epa.gov>  
Cc: "Young, Howard S." <younghs@cdmsmith.com>, "Coffey, Scott" <CoffeySE@cdmsmith.com>  
Subject: Portland Harbor Surface Sediment Sampling

Sean and Davis,  
Find attached photos SG-S199 in swan island lagoon RM 8.3:

1st photo: sample area is  $>3/4$  covered by dock structures and docked rafts and boats.

2nd photo: low recovery and debris are issues at this location.

Thank you,  
Julee

Sent from my Verizon, Samsung Galaxy smartphone